Number of schools responding to survey: 1,589

Which best describes the location of your school building?

159	10.01%	Large Central City (Population greater than 400,000 and density greater than 6,000.)
315	19.82%	Mid-Size Central City (Population less than 400,000 and density less than 6,000.)
208	13.09%	Urban Fringe of Large City (Defined as urban by the Census Bureau.)
169	10.64%	Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)
26	1.64%	Large Town (Population greater than or equal to 25,000.)
274	17.24%	Small Town (Population less than 25,000 and greater than or equal to 2,500.)

A. PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. When was the school originally constructed?

27.56%

438

Pre-1900	38	2.40%	1930-1939	106	6.69%	1970-1979	140	8.83%
1900-1909	35	2.21%	1940-1949	35	2.21%	1980-1989	45	2.84%
1910-1919	57	3.60%	1950-1959	402	25.36%	1990-1999	184	11.61%
1920-1929	124	7.82%	1960-1969	419	26.44%			

Rural (Population less than 2,500 and coded rural by the Census Bureau.)

5. In your opinion, is this school building overcrowded?

Yes 426 **26.88%** No 1.159 **73.12%**

6. If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?

No Renovation	462	29.15%	1940-1949	4	0.25%	1970-1979	99	6.25%
Before 1930	20	1.26%	1950-1959	61	3.85%	1980-1989	142	8.96%
1930-1939	1	0.06%	1060_1060	135	8 52%	1000 1000	661	44 700/

7. How many total square feet does the original building have?

Minimum: 600 Maximum: 447,130 Median: 45,420 Average: 62,865

8. If the building has been renovated or added on to, how many total square feet exist now?

Minimum: 3,104 Maximum: 870,003 Median: 63,000 Average: 87,415

9. How many portable classrooms were in use during the 1998-99 school year?

Number of schools reporting the use of portable classrooms: 108

Minimum: 1 Maximum: 40 Median: 2 Average: 4

10. Does the school accommodate any of its students in instructional facilities located OFF-SITE?

Yes 110 6.94% No 1,475 93.06%

11. How many of this school's FTE students are located in OFF-SITE facilities?

Number of schools reporting OFF-SITE facilities: 110

Minimum: 1 Maximum: 200 Median: 13 Average: 31

Definitions for questions #12 and #15:

Excellent: New or easily restorable to "like new" only minimal routine maintenance.

Good: Only routine maintenance or minor repair required.

Adequate: Some preventive maintenance and/or corrective repair required.

Fair: Fails to meet code and functional requirement in some cases; extensive repair.

Poor: Consistent substandard performance; major corrective repair or overhaul.

Replace: Non-operational or significantly substandard performance. Replacement

NA: Not Applicable

12. What is the overall condition of the original buildings and the permanent additions?

	Excellent	Good	Adequate	Fair	Poor	Replace	NA
Original Buildings:	248	517	565	167	46	27	15
	15.65%	32.62%	35.65%	10.54%	2.90%	1.70%	0.95%
Permanent Additions:	330	421	315	92	22	8	397
	20.82%	26.56%	19.87%	5.80%	1.39%	0.50%	25.05%

13. What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition?
Number of schools reporting cost for repairs/renovations/modernizations:
881
Statewide Total Costs = \$1,558,104,085

Minimum: \$8,000 Maximum: \$27,676,000 Median: \$695,000 Average: \$1,768,563

14. On which of the sources listed below is this estimate based? Choose all that apply.

26.75% Does not apply--already in good (or better) overall condition.
 17.53% Facilities inspection/assessment performed within the last three years by licensed professionals.
 12.28% Repair/renovation/modernization work already being performed/contracted for.
 19.10% Capital improvement/facilities master plan or schedule.

199 19.10% Capital improvement/lacilities master plan or scriedul

475 18.18% My best professional judgement.

161 **6.16%** Opinions of others.

15. Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?

	Excellent	Good	Adequate	Fair	Poor	Replace
Roofs:	343	663	354	132	67	26
	21.64%	41.83%	22.33 %	8.33%	4.23%	1.64%
Framing, floors, foundations:	346	792	336	78	27	6
	21.83%	49.97%	21.20%	4.92%	1.70%	0.38%
Exterior walls, finishes, windows, doors:	307	602	390	211	59	16
	19.37%	37.98%	24.61%	13.31%	3.72%	1.01%
Interior finishes, trims:	270	784	400	98	27	6
	17.03%	49.46%	25.24%	6.18%	1.70%	0.38%
Plumbing:	249	603	539	119	58	17
	15.71%	38.04%	34.01%	7.51%	3.66%	1.07%
Heating ventilation, air conditioning:	243	535	465	230	85	27
	15.33%	33.75%	29.34%	14.51%	5.36%	1.70%
Electrical power:	328	582	344	199	119	13
	20.69 %	36.72%	21.70%	12.56 %	7.51%	0.82%
Electrical lighting:	348	757	319	117	37	7
	21.96%	47.76%	20.13%	7.38%	2.33%	0.44%
Life safety requirements (e.g., emergency lighting and warning systems, exit signs):	405	773	290	79	24	14
	25.55%	48.77%	18.30%	4.98%	1.51%	0.88%

16	How adamieta is usus sussessi	4 : 4							
10.	How adequate is your curren Very Adequate: 1	t maintenan 12 7.07 %	ce buaget to					dition?	
	• •	68 35.84%			hat Adequate: dequate at all:		45.17% 11.92%		
	·				·				
17.	How satisfactory or unsatisfa			wing enviro	nmental factors	in this	school's C	N-SITE buildii	ngs?
		•	Satisfactory		sfactory	Uns	atisfactory	Very Un:	satisfactory
	Lightir	J	24.16%	1,080	68.14%	118	7.44%	4	0.25%
	Heatir	•	19.75%	1,098	69.27%	161	10.16%	4	0.82%
	Ventilatio	on: 263	16.59%	1,039	65.55%	257	16.21%	26	1.64%
	Indoor air quali	•	17.60%	1,090	68.77%	198	12.49%	18	1.14%
	Acoustics for noise contr	ol: 250	15.77%	1,139	71.86%	183	11.55%	13	0.82%
	Flexibility of instructional space	e: 217	13.69%	826	52.11%	462	29.15%	80	5.05%
	Energy efficiency/conservation	on: 262	16.53%	921	58.11%	367	23.15%	35	2.21%
	Physical security of building	is: 237	14.95%	1,090	68.77%	227	14.32%	31	1.96%
	Exterior nois	se: 399	25.17%	1,105	69.72%	69	4.35%	12	0.76%
18.	How many instructional class Total number of inst	rooms were ructional cla	in use as or ssrooms rep	f the third Fi ported in us	riday in Septem e as of the third	ber, 19 Friday	98? in Septem	nber, 1998: 4	7,521
	Minimum: 1	Maximu	ım: 142		Median:	25		Average:	30
19.	Does the school building have	e CENTRAL	. air conditio	ning (cools	all interior space	e)?			
	Yes 365 23.03%		1,220 76.9 3		•	-,			
20	Doos this school have air con	editionina in	im m4 4 i 1					_	
20.	Does this school have air con 394 31.07% Yes. ir	ning in instructions			s, computer labs	s, and/c	or the librai	y?	
		r mstructiona r computer la		IS.					
	,	the library.							
24		-							
21.	How many instructional class			ning?		_			
	<i>Minimum:</i> 1	Maximu	<i>ım:</i> 119		Median:	5		Average:	11
22.	Does this school have a sepa	rate room fo	or a library/re	esource/me	dia center?				
	Yes 1,529 96.47%	No	56 3.5 3	3%					
23.	How does the size of your scl in your building?	hool's library	/resource/m	nedia center	compare with t	he size	of a typica	al classroom	
	Smaller: 30 1.95%	About	the same si	ize: 177	11.52%	Larg	er: 1,329	86.52%	
24.	How many classrooms would	fit in the spa	ace used for	your library	//resource/medi	a cente	er?		
	Minimum: 12	Maximu	<i>m</i> : 3		Median:	3		Average:	3
25.	If you have a library/resource/	/media cente	er is it staffe	ed by a licen	ised profession	al lihra	rian?		
	Yes 1.334 86.85%		202 13 14		ecu, profession	ui iibi a	iui:		

26. What percent time is your library/resource/media center staffed by a licensed, professional librarian?

Number of schools reporting library/resource/media center staffed by licensed, professional librarian: 1,334

Minimum: 3% Maximum: 100% Median: 100% Average: 81.45%

27. Does this school have a separate room for a parent/family center?

Yes 304 19.18% No 1,281 80.82%

28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building?

Smaller.

134 44.08%

About the same size:

132 43.42%

Larger:

38 **12.50%**

29. How many classrooms would fit in the space used for the parent/family center?

Minimum:

.17

Maximum:

16

Median:

1

Average:

1

B. SCHOOL SAFETY

30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)?

914 57.63%

No 672 42.37%

31. Does your school have a "Check-In" policy for school visitors?

Yes 1,531 96.53%

No 55 3.47%

32. Does your school have an established emergency response plan for dealing with school safety issues?

Yes 1,527 96.28%

No 59 3.72%

33. Does your school have on-site security provided by police officers or private security guards?

Yes 196 **12.36%** No 1,390 87.64%

34. Does your school have parent or other community volunteers to assist in monitoring the school?

226 14.25% Yes

No 1,360 85.75%

35. Does your school have metal detectors?

Yes 28 1.77%

No 1,558 98.23%

36. Does your school have surveillance cameras located within the school building or on school grounds?

Yes 118 **7.44%** No 1,468 **92.56%**

C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY

ELEMENTARY SCHOOLS ONLY Educational Appropriateness:

Number of Elementary Schools Reported:

994

38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:

244 21.55%

Disagree with statement:

182 **16.08%**

Agree with statement:

685 **60.51%**

Strongly disagree with statement:

21 1.86%

39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant.

Strongly agree with statement:

306 27.13%

Disagree with statement:

146 **12.94%**

Agree with statement:

632 **56.03%**

Strongly disagree with statement:

3.90% 44

40.	Adequate space is available for	small w	ork group ir	estruction (less than 15 students).		
	Strongly agree with statement:	236	20.94%	Disagree with statement:	362	32 12%
	Agree with statement:	479	42.50%	Strongly disagree with statement:	50	4.44%
41.	Adequate space is available to	allow ins	structional c	lassrooms to maintain a class size of less than s	30 stude	ents.
	Strongly agree with statement:	359	31.85%	Disagree with statement:	206	18.28%
	Agree with statement:	542	48.09%	Strongly disagree with statement:	20	1.77%
42.	Adequate space is available for	large w	ork group in	struction (more than 30 students).		
	Strongly agree with statement:	158	14.02%	Disagree with statement:	501	44.45%
	Agree with statement:	362	32.12%	Strongly disagree with statement:	106	9.41%
43.	Equipment and furniture (such a population.	ıs shelv	ing units, ta	bles, and chairs) are the appropriate size for the	buildin	g's student
	Strongly agree with statement:	373	33.10%	Disagree with statement:	42	3.73%
	Agree with statement:	708	62.82%	Strongly disagree with statement:	4	0.35%
Bui	Iding Suitability for Education	;				
44.	Buildings materials, color schen	nes, and	decor prov	ide impetus to learning.		
	Strongly agree with statement:	290	25.73%	Disagree with statement:	174	15.44%
	Agree with statement:	647	57.41%	Strongly disagree with statement:	16	1.42%
45.	Drinking fountain and restroom conveniently located.	facilities	are an app	ropriate height and size for the school building p	opulatio	on and
	Strongly agree with statement:	320	28.39%	Disagree with statement:	136	12.07%
	Agree with statement:	656	58.21%	Strongly disagree with statement:	15	1.33%
46.	Student services areas (e.g., co	unselor	and medica	nl) ensure privacy and are of sufficient size.		
	Strongly agree with statement:	219	19.45%	Disagree with statement:	375	33.30%
	Agree with statement:	451	40.05%	Strongly disagree with statement:	81	7.19%
47.	Building is accessible to student	ts with c	lisabilities.			
	Strongly agree with statement:	366	32.50%	Disagree with statement:	155	13.77%
	Agree with statement:	488	43.34%	Strongly disagree with statement:	117	10.39%
48.	Space is available and appropri	ate for e	extended da	y learning opportunities, including before and af	ter scho	ol day care.
	Strongly agree with statement:	197	17.84%	Disagree with statement:	263	23.82%
	Agree with statement:	610	55.25%	Strongly disagree with statement:	34	3.08%
Sch	nool Site Suitability:					
49.	Site is large enough to meet edu	ıcationa	nl needs and	l is accessible.		
	Strongly agree with statement:	343	30.76%	Disagree with statement:	159	14.26%
	Agree with statement:	581	52.11%	Strongly disagree with statement:	32	2.87%

50.	Site has a safe outdoor space v	vhere c	hildren can engage in	a variety of games, sports, and motor	· activiti	es.
	Strongly agree with statement:	413	36.68%	Disagree with statement:	73	6.48%
	Agree with statement:	616	54.71%	Strongly disagree with statement:	24	2.13%
51.	Student loading areas are segre	egated :	from other vehicular ti	raffic and pedestrian walkways.		
	Strongly agree with statement:	158	14.03%	Disagree with statement:	433	38.45%
	Agree with statement:	406	36.06%	Strongly disagree with statement:	129	11.46%
Pla	yground Site and Equipment S	uitabil	ity:			
52.	Playground size is appropriate t	or num	ber of students.			
	Strongly agree with statement:	359	31.88%	Disagree with statement:	145	12.88%
	Agree with statement:	573	50.89%	Strongly disagree with statement:	49	4.35%
53.	Playgrounds are separated from	n street	s and parking areas v	vith fencing or other permanent materi	al.	
	Strongly agree with statement:	288	25.58%	Disagree with statement:	258	22.91%
	Agree with statement:	525	46.63%	Strongly disagree with statement:	55	4.88%
54.	Playgrounds are well equipped	and ap	oropriate for age level	ls.		
	Strongly agree with statement:	248	22.02%	Disagree with statement:	204	18.12%
	Agree with statement:	633	56.22%	Strongly disagree with statement:	41	3.64%
55.	Playground equipment is access	sible to	students with disabili	ties.		
	Strongly agree with statement:	160	14.21%	Disagree with statement:	412	36.59%
	Agree with statement:	482	42.81%	Strongly disagree with statement:	72	6.39%
56.	Playground equipment is free or	f sharp	edges, of sound cons	struction, and in good condition.		
	Strongly agree with statement:	294	26.11%	Disagree with statement:	96	8.53%
	Agree with statement:	711	63.14%	Strongly disagree with statement:	25	2.22%
	DDLE, JUNIOR HIGH, AND Fucational Appropriateness:	IIGH S	CHOOLS ONLY	Number of Secondary Schools	Danad	ad. 505
	• • •			Number of Secondary Schools	•	
57.	Size of instructional classrooms objectives.	are lar	ge enough to allow fo	r alternative room arrangements to fac	ilitate c	urricular
	Strongly agree with statement:	145	22.83%	Disagree with statement:	108	17.01%
	Agree with statement:	372	58.58%	Strongly disagree with statement:	10	1.57%
58.	Size and design of special learn compatible with instructional ne		as (science labs, art,	technology education, music and spec	ial educ	cation) is
	Strongly agree with statement:	170	26.81%	Disagree with statement:	140	22.08%
	Agree with statement:	290	45.74%	Strongly disagree with statement:	34	5.36%
59 .	Adequate space is available for	small v	vork group instruction	(less than 15 students).		
	Strongly agree with statement:	153	24.13%	Disagree with statement:	148	23.34%
	Agree with statement:	315	49.68%	Strongly disagree with statement:	18	2.84%

60. Adequate space is available to	allow in	structional	classrooms to maintain a class size of less than	30 stud	lents.
Strongly agree with statement:	226	35.65%	Disagree with statement:	88	13.88%
Agree with statement:	310	48.90%	Strongly disagree with statement:	10	1.58%
61. Adequate space is available for	r large v	vork group i	nstruction (more than 30 students).		
Strongly agree with statement:	106	16.72%	Disagree with statement:	262	41.32%
Agree with statement:	221	34.86%	Strongly disagree with statement:	45	7.10%
Building Suitability for Education):				
62. Buildings materials, color schei	mes, an	d decor pro	vide impetus to learning.		
Strongly agree with statement:	180	28.39%	Disagree with statement:	84	13.25%
Agree with statement:	352	55.52%	Strongly disagree with statement:	18	2.84%
63. Drinking fountain and restroom conveniently located.	facilities	s are an app	ropriate height and size for the school building p	opulatio	on and
Strongly agree with statement:	217	34.23%	Disagree with statement:	54	8.52%
Agree with statement:	352	55.52%	Strongly disagree with statement:	11	1.74%
64. Student services areas (e.g., c	ounselo	r and medic	al) ensure privacy and are of sufficient size.		
Strongly agree with statement:	153	24.13%	Disagree with statement:	130	20.50%
Agree with statement:	317	50.00%	Strongly disagree with statement:	34	5.36%
65. Building is accessible to studer	nts with	disabilities.			
Strongly agree with statement:	237	37.38%	Disagree with statement:	62	9.78%
Agree with statement:	309	48.74%	Strongly disagree with statement:	26	4.10%
66. Space is available and appropr	riate for	extended da	ay learning opportunities, including before and a	fter sch	ool day care.
Strongly agree with statement:	111	17.51%	Disagree with statement:	151	23.82%
Agree with statement:	338	53.31%	Strongly disagree with statement:	34	5.36%
School Site Suitability:					
67. Site is large enough to meet ed	lucation	al needs an	d is accessible.		
Strongly agree with statement:	186	29.34%	Disagree with statement:	90	14.20%
Agree with statement:	326	51.42%	Strongly disagree with statement:	32	5.05%
68. Site has a safe outdoor space to	where s	tudents can	engage in a variety of games, sports, and moto	r activiti	ies.
Strongly agree with statement:	201	31.70%	Disagree with statement:	57	8.99%
Agree with statement:	349	55.05%	Strongly disagree with statement:	27	4.26%
69. Student loading areas are segr	egated	from other v	rehicular traffic and pedestrian walkways.		
Strongly agree with statement:	88	13.88%	Disagree with statement:	253	39.91%
Agree with statement:	219	34.54%	Strongly disagree with statement:	74	11.67%